


INSTALLATION PROCEDURE OF THE D-BOX USB ON WINDOWS VISTA

Connect the D-Box USB cable to the computer.


Caution !! If you move the cable from one port to another one, it will be necessary to make a new installation on the new port.

A first screen indicates you that a new material is detected :




Select the button « **Research and installation of the driver (recommended)** »

The following window appear and ask you to insert the CD ROM of the drivers.






At the moment the drivers are not included on the CD ROM delivered with USB cable. For the reason select the button « **I have not that CD ROM. Indicates me other options** ».



Select the button « **Manual search of the driver on the computer (advanced)** »

Select the directory where the enclosed drivers have been copied.




Select **Next**.






A security screen indicates you that the driver is not approved by Microsoft :




Select the button **Installation of that driver**

The installation **starts** :





The USB cable is now installed



Select **Close** to exit the installer.


Check the of the port number where the cable has been installed

Caution !!! The cable must be connected to the computer.






Open the configuration board of your computer :




Select the **System** application





Start the device driver



Check in the port menu (COM et LPT), the number of the virtual port used by the USB cable called **Xiring USB Serial Port** or **Xiring USB COMM Port**

